

EXISTING FIBERGLASS WALL (INTERIOR)

EXISTING EXTERIOR FIBERGLASS TRUNK CABIN

FIBERGLASS PANEL CUT OUT FROM INTERIOR WALL

USED 3/4" LUMBER THROUGHOUT EXCEPT TOP & BOTTOM "A" & "B" USED 1/2" TO MAXIMIZE INTERIOR HEIGHT

CHECK BOAT FOR CLEARANCE AND ADJUST DEPTH IF NECESSARY.

